## Town of Scituate Tree Warden & Planning Board NOTICE OF PUBLIC HEARING

In accordance with Massachusetts General Laws (MGL), Chapter 87, Public Shade Tree Law, Section 3 (Cutting of Public Shade Trees; Hearing; Damages), and MGL Chapter 40, Section 15c, the Scenic Road Act, the Town of Scituate Tree Warden and Planning Board will hold a Public Hearing regarding an application from National Grid to remove or prune public shade trees and trees on Scenic Roads at 8:00 PM on March 13, 2014 in the Selectmen's Meeting Room, Town Hall, 600 Chief Justice Cushing Hwy, Scituate, MA. Any person interested or wishing to be heard on this matter should appear at the time and place designated.

The program includes a tree-by-tree hazard assessment of public and private trees, along the main three-phase lines that serve the community. In order to reduce tree outage problems affecting large numbers of customers served by these main lines, National Grid's arborists have identified seventeen (17) town-owned trees for removal along town roads. Town trees located within the public way that are designated for removal are posted in the field with a notice of public hearing.

The roads with town trees affected by the program are as follows: eleven tree removals on Country Way, two on Stockbridge Road, one removal on First Parish Road (designated Scenic Roads) and three removals on Driftway (not designated a Scenic Road).

A complete list of town trees designated for removal including information about the location, size and species of the affected trees and the reason for work proposed, is available at the Planning Board office at Town Hall and the Tree Warden's Office at the DPW Highway Garage on Captain Pierce Road during normal business hours.

William Limbacher Chairman, Planning Board

George Story Tree Warden



## Town of Scituate (Town-owned Trees)

House #         Location         Pole #         Dia.         Species         # Stem         Defect Condition           296         AF         529         16         R.Maple         Base decay           296         527-626         12         Elm         Dead           258         518-517         15         Ash         Trunk decay @ 16 ft           Pump station         AP         508-507         12         Ash         Base decay           Pump station         508-507         19         Ash         Decline           Pump station         508-507         26         Ash         Decline           Pump station         508-507         26         Ash         Decline           Pump station         508-507         36         Ash         Decline           199         AF         508-507         36         Ash         Decline           191         478-477         40         H.Chestnut         Hollow base widecay           101         AF         62-61         22         Locust         Base, root decay           Lot         AF         40         16         R.Maple         Base decay           Lot         AF         62-61         <	Town of Scituate	Town of Scituate			***************************************					
lame         House #         Location         Pole #         Dia.         Species         # Stem         Defect Condition           296         AF         529         16         RMaple         Base decay           258         518-517         12         Elm         Dead           Pump station         AP         508-507         12         Ash         Base decay           Pump station         508-507         12         Ash         Decline           Pump station         508-507         26         Ash         Decline           199         AF         508-507         26         Ash         Decline           199         AF         508-504         24         N/Maple         Internal decay; ants.           101         AF         62-61         22         Locust         Dead top           Lot         AF         47 </th <th>Hazard Tree</th> <th>Removal List</th> <th></th> <th></th> <th></th> <th></th> <th></th> <th></th> <th></th> <th></th>	Hazard Tree	Removal List								
Street Name         House #         Location         Pole #         Dia.         Species         # Stem         Defect Condition           Country Way         296         AF         529         12         Elm         Dead           Country Way         Pump station         AP         529-526         12         Elm         Dead           Country Way         Pump station         508-507         17         Ash         Base decay           Country Way         Pump station         508-507         19         Ash         Decline           Country Way         Pump station         508-507         26         Ash         Decline           Country Way         Pump station         508-507         24         Ash         Decline           Country Way         Pump station         508-507         24         Ash         Decline           Country Way         199         AF         508-504         24         N.Maple         Internal decay; ants, fungi           Country Way         191         AF         62-602         22         Locust         Decline           Country Way         Lot         AF         62-61         20         R.Oak         Base, root decay.           Driffway <th>Circuit #: 91</th> <th>5W36</th> <th></th> <th>***************************************</th> <th>**************************************</th> <th></th> <th></th> <th></th> <th></th> <th></th>	Circuit #: 91	5W36		***************************************	**************************************					
Country Way         305         AF         529         16         R.Maple         Base decay           Country Way         296         527-526         12         Elm         Dead           Country Way         Pump station         508-507         12         Ash         Base decay         16 ft           Country Way         Pump station         508-507         12         Ash         Decline           Country Way         Pump station         508-507         19         Ash         Decline           Country Way         Pump station         508-507         36         Ash         Decline           Country Way         Pump station         508-507         36         Ash         Decline           Country Way         Light         AF         508-507         36         Ash         Decline           Country Way         191         AF         508-504         24         N.Maple         Internal decay; ants           Country Way         Lot         AF         62-61         20         H.Chestrut         Hollow base widecay           Driffway         Lot         AF         62-61         20         R.Oak         Base decay           Driffway         Lot         AF	Site ID	Street Name	House #	Location	Pole #	Dia.	Species	# Stem	Defect Condition	Work Proposed
Country Way         296         527-526         12         Elm         Dead           Country Way         258         518-517         15         Ash         Trunk decay @ 16 ft           Country Way         Pump station         508-507         19         Ash         Base decay           Country Way         Pump station         508-507         19         Ash         Decline           Country Way         Pump station         508-507         26         Ash         Decline           Country Way         Pump station         508-507         36         Ash         Decline           Country Way         199         AF         605-504         24         N.Maple         Internal decay; ants           Country Way         76         AF         62-504         24         N.Maple         Internal decay; ants           Country Way         76         AF         62-61         20         R.Cak         Base, root decay; ants, fungi           Driftway         Lot         AF         62-61         20         R.Cak         Base, root decay; ants, fungi           Driftway         Lot         AF         62-61         20         R.Cak         R.Cak           Stockbridge Rd         97	RK23	Country Way	305	AF	529	16	R.Maple		Base decay	Remove
Country Way         258         518-517         15         Ash         Trunk decay @ 16 ft           Country Way         Pump station         508-507         12         Ash         Base decay           Country Way         Pump station         508-507         26         Ash         Decline           Country Way         Pump station         508-507         26         Ash         Decline           Country Way         Pump station         508-507         36         Ash         Decline           Country Way         199         AF         508-507         36         Ash         Decline           Country Way         199         AF         508-507         36         Ash         Decline           Country Way         191         508-507         36         Ash         Decline           Country Way         76         478-477         40         H.Chestrut         Hollow base widecay.           Country Way         Lot         AF         62-61         20         R.Oak         Base, root decay.           Driftway         Lot         AF         62-61         20         R.Oak         Base, root decay.           Slockkridge Rd         97         AF         40         R.Oa	RK24	Country Way	296		527-526	12	ᇤ		Dead	Remove
Country Way         Pump station         AP         508         17         Ash         Base decay           Country Way         Pump station         508-507         12         Ash         Decline           Country Way         Pump station         508-507         26         Ash         Decline           Country Way         Pump station         508-507         36         Ash         Decline           Country Way         199         AF         505-504         24         N.Maple         Internal decay; ants           Country Way         191         AF         505-504         24         N.Maple         Internal decay; ants           Country Way         191         AF         605-504         24         N.Maple         Internal decay; ants           Country Way         191         AF         605-504         24         N.Maple         Base, root decay, ants, fungi           Country Way         Lot         AF         62-61         20         R.Oak         Base, root decay, ants, fungi           Driftway         Lot         AF         62-61         20         R.Oak         Base, root decay, ants, fungi           Stockbridge Rd         97         AF         40         N.Maple         3	RK27	Country Way	258		518-517	15	Ash		Trunk decay @ 16 ft	Remove
Country Way         Pump station         508-507         12         Ash         Base decay           Country Way         Pump station         508-507         26         Ash         Decline           Country Way         Pump station         508-507         26         Ash         Decline           Country Way         Pump station         508-507         24         N.Maple         Internal decay; ants. fungi           Country Way         199         AF         503-504         43         R.Oak         Base, root decay, ants. fungi           Country Way         Lot         AF         62-61         20         R.Oak         Base, root decay, ants. fungi           Driftway         Lot         AF         62-61         20         R.Oak         Base, root decay, ants. fungi           Driftway         Lot         AF         62-61         20         R.Oak         Base, root decay           Stockbridge Rd         226/220         AF         14-15         20         Ash         3         Decline           Stockbridge Rd         97         AF         40         N.Maple         Decay in multiple areas           First Parish Rd         92         21-20         0         N.Dack         Decay in multiple areas	RK28A	Country Way	Pump station	AP	508	17	Ash		Base decay	Remove
Country Way         Pump station         508-507         19         Ash         Decline           Country Way         Pump station         508-507         26         Ash         Decline           Country Way         199         AF         508-504         24         N.Maple         Intermal decay; ants, fungi           Country Way         191         505-504         24         N.Maple         Intermal decay; ants, fungi           Country Way         76         AF         603-502A         22         Locust         Hollow base w/decay, ants, fungi           Driftway         Lot         AF         62-61         20         R.Oak         Base, root decay, ants, fungi           Driftway         Lot         AF         62-61         20         R.Oak         Base, root decay           Stockbridge Rd         226/220         AF         14-15         20         Ash         Decline           Stockbridge Rd         97         AF         40         N.Maple         Decline           First Parish Rd         92         21-20         40         N.Maple         Decay in multiple areas	RK28A	Country Way	Pump station		508-507	12	Ash		Base decay	Remove
Country Way         Pump station         508-507         26         Ash         Decline           Country Way         Pump station         508-507         36         Ash         Decline           Country Way         199         AF         508-504         43         R.Oak         Base, roof decay; ants           Country Way         191         503-502A         43         R.Oak         Base, roof decay, ants, fungi           Country Way         161         AF         63-62         22         Locust         Dead top           Driffway         Lot         AF         63-62         22         Locust         Base, roof decay           Driffway         Lot         AF         62-61         20         R.Oak         Base, roof decay           Driffway         Lot         AF         62-61         12         R.Oak         Base, roof decay           Stockbridge Rd         97         AF         14-15         20         Ash         Bese, roof decay           Stockbridge Rd         97         AF         40         16         R.Maple         3         Decline           Stockbridge Rd         92         21-20         40         N.Maple         Decay in multiple areas	RK28A	Country Way	Pump station		508-507	19	Ash		Decline	Remove
Country Way         Pump station         508-507         36         Ash         Decline           Country Way         199         AF         505-504         24         N.Maple         Internal decay; ants           Country Way         191         AF         503-502A         43         R.Oak         Base, root decay, ants, fungi           Country Way         76         AF         678-62A         22         Locust         Hollow base w/decay           Driftway         Lot         AF         62-61         20         R.Oak         Base, root decay           Driftway         Lot         AF         62-61         20         R.Oak         Base, root decay           Driftway         Lot         AF         62-61         20         R.Oak         Base, root decay           Stockbridge Rd         97         AF         40         16         R.Maple         3         Decline           Stockbridge Rd         97         AF         40         N.Maple         3         Decline           First Parish Rd         92         21-20         40         N.Maple         Decay in multiple areas	RK28A	Country Way	Pump station		508-507	26	Ash		Decline	Remove
Country Way         199         AF         505-504         24         N.Maple         Internal decay; ants           Country Way         191         503-502A         43         R.Oak         Base, root decay, ants, fungi           Country Way         76         AF         67-67         22         Locust         Hollow base w/decay           Driftway         Lot         AF         62-61         20         R.Oak         Base, root decay           Driftway         Lot         AF         62-61         12         R.Oak         Base decay           Stockbridge Rd         97         AF         40         16         R.Maple         3         Decline           Stockbridge Rd         92         21-20         40         N.Maple         Decay in multiple areas           First Parish Rd         92         21-20         40         N.Maple         Total Removals:	RK28A	Country Way	Pump station		508-507	36	Ash		Decline	Remove
Country Way         191         503-502A         43         R.Oak         Base, root decay, ants, fungi           Country Way         76         AF         63-62         22         Locust         Hollow base w/decay           Driftway         Lot         AF         62-61         20         R.Oak         Base, root decay           Driftway         Lot         AF         62-61         12         R.Oak         Base decay           Stockbridge Rd         226/220         AF         14-15         20         Ash         3         Decline           Stockbridge Rd         97         AF         40         16         R.Maple         3         Decline           First Parish Rd         92         21-20         40         N.Maple         Decay in multiple areas	RK30	Country Way	199	AF	505-504	24	N.Maple		Internal decay; ants	Remove
Country Way         76         478-477         40         H.Chestnut         Hollow base w/decay           Driftway         Lot         AF         63-62         22         Locust         Dead top           Driftway         Lot         AF         62-61         20         R.Oak         Base, root decay           Driftway         Lot         AF         62-61         12         R.Oak         Base decay           Stockbridge Rd         97         AF         40         16         R.Maple         3         Decline           First Parish Rd         92         21-20         40         N.Maple         Decay in multiple areas         Incomparison	RK31	Country Way	191		503-502A	43	R.Oak		Base, root decay, ants, fungi	Remove
Driftway         Lot         AF         63-62         22         Locust         Dead top           Driftway         Lot         AF         62-61         20         R.Oak         Base, root decay           Driftway         Lot         AF         62-61         12         R.Oak         Base decay           Stockbridge Rd         97         AF         40         16         R.Maple         3         Decline           First Parish Rd         92         21-20         40         N.Maple         Decay in multiple areas         Incomparison           First Parish Rd         92         1-20         40         N.Maple         Total Removals:	RK37	Country Way	76		478-477	40	H.Chestnut		Hollow base w/decay	Remove
Driftway         Lot         AF         62-61         20         R.Oak         Base, root decay           Driftway         Lot         AF         62-61         12         R.Oak         Base decay           Stockbridge Rd         226/220         AF         14-15         20         Ash         3         Decline           Stockbridge Rd         97         AF         40         16         R.Maple         3         Decline           First Parish Rd         92         21-20         40         N.Maple         Decay in multiple areas           First Parish Rd         92         21-20         40         N.Maple         Total Removals:	RK44	Driffway	Ę	AF	63-62	22	Locust		Dead top	Remove
Driftway         Lot         AF         62-61         12         R.Oak         Base decay           Stockbridge Rd         226/220         AF         14-15         20         Ash         3         Decline           Stockbridge Rd         97         AF         40         16         R.Maple         3         Decline           First Parish Rd         92         21-20         40         N.Maple         Decay in multiple areas           First Parish Rd         92         21-20         40         N.Maple         Total Removals:	RK44	Driftway	ğ	AF	62-61	20	R.Oak		Base, root decay	Remove
Stockbridge Rd         226/220         AF         14-15         20         Ash         3         Decline           Stockbridge Rd         97         AF         40         16         R.Maple         3         Decline           First Parish Rd         92         21-20         40         N.Maple         Decay in multiple areas           First Parish Rd         92         21-20         40         N.Maple         Total Removals:	RK44	Driftway	Lot	AF	62-61	12	R.Oak		Base decay	Remove
Stockbridge Rd         97         AF         40         16         R.Maple         3         Decine           First Parish Rd         92         21-20         40         N.Maple         Decay in multiple areas           Image: Apple of the problem of the pro	RK52	Stockbridge Rd	226/220	AF	14-15	20	Ash	က	Decline	Remove
First Parish Rd 92 21-20 40 N.Maple Decay in multiple areas  Total Removals:	RK59	Stockbridge Rd	97	AF	40	16	R.Maple	က	Decline	Remove
	RK63	First Parish Rd	92		21-20	40	N.Maple		Decay in multiple areas	Remove
		1. (, d, m, t, d, mm)							Total Removals:	: 17
									um ( 1 6 8 9 ) 5 ° 4 mm	

